



ø8 mm









- (D) Montageanleitung
- (NL) Handleiding voor de montage
- (TR) Montaj talimatı
- (FR) Instructions de montage
- (CZ) Montážní návod
- (HU) Összeszerelési útmutató

- (GB) Assembly instructions
- (PL) Instrukcja montażu
- (RU) Инструкция по монтажу
- (IT) Istruzioni di montaggio
- (RO) Instrucțiuni de asamblare
- (SK) Montážny návod

# SALVADOR SAD52T50

2 / 6

1





# SALVADOR SAD52T50

3 / 6

2




M1  x8



3

M1  x8


C3  x16





# SALVADOR SAD52T50


4 / 6

4

**(B3)**   $\phi$  8x45 mm x8

**(K3)**   $\phi$  7x70 mm x8




**(IM4)**  S=4 mm x1







# SALVADOR SAD52T50

5 / 6

5

- 1   $\varnothing 8 \text{ mm}$
- 2 
- 3 





## ZUBEHÖR BELEUCHTUNG 026034ZB

