







- (D) Montageanleitung
- (NL) Handleiding voor de montage
- (TR) Montaj talimatı
- (FR) Instructions de montage
- (CZ) Montážní návod
- (HU) Összeszerelési útmutató

- (GB) Assembly instructions
- (PL) Instrukcja montażu
- (RU) Инструкция по монтажу
- (IT) Istruzioni di montaggio
- (RO) Instrucțiuni de asamblare
- (SK) Montážny návod

SALVADOR SAD52T51

2 / 6

1




SALVADOR SAD52T51

3 / 6

2


M1  x4



3

M1  x4


C3  x8





SALVADOR SAD52T51


4 / 6

4





B3  ϕ 8x45 mm x4


K3  ϕ 7x70 mm x4

IM4  S=4 mm x1



5





ZUBEHÖR BELEUCHTUNG 06084ZB

