





















# agata



x1



5MIN

<p>A x1</p> 	<p>H x5</p> 	<p>1</p> 	<p>2</p> 	<p>3</p> 
<p>B x1</p> 	<p>I x4</p>  <p>M6x20mm</p>			
<p>C x1</p> 	<p>J x2</p>  <p>M6x25mm</p>	<p>4</p> 	<p>5</p> 	<p>6</p> 
<p>D x2</p> 	<p>K x8</p>  <p>M6x30mm</p>			
<p>E x1</p> 	<p>L a x4</p>  <p>b x2</p> 			
<p>F x1</p> 	<p>M x1</p> 			
<p>G x1</p> 				

KEAVI  
C5030A

1/1