



ECCE XJH-20S-14


Ax1 M4	Bx11 M6x12	Cx2 M6x30	Dx4 M6x40
Ex4 M6x48	Fx4 M3.5x35	Gx8 M3.5x12	Hx4 M7x48
Ix8 Ø8x30	Jx8 M6x32	Kx8 Ø15x8	



① x1




⑤ x1




⑨ x1




⑭ x1




② x1




⑥ x1




⑩ x2




⑮ x1




③ x1



⑦ x1




⑪ x1




⑯ x2



⑫ x1




⑰ x1



④ x1




⑧ x1




⑬ x1


1



2




3



Ix4



4




Ax1



Hx4




5




Ax1

Ex4



6




Ax1

Bx4




7




Ax1




Cx2



Dx4



8




Ax1



Bx4




9



Fx4



10



Kx4


Jx4

Jx4

Kx4




11




Gx4



12



13



Ax1



Bx3



14

