











 <p>FARN F313</p>	<p>A.(M6*20)x10</p> 	<p>B.(M6*30)x2</p> 	<p>C.(\varnothing18*\varnothing6.5*1.5) x12</p> 
	<p>D.(\varnothing20*\varnothing8*8)x2</p> 	<p>E.(3*90*90)x1</p> 	<p>F.(M4)x1</p> 



 <p>① x1</p>	 <p>② x1</p>	 <p>③ x1</p>	 <p>④ x1</p>
--	---	--	---

