





















 <p>HARBORE DC1145</p>	<p>A</p>  <p>M6x40mm 4x</p>	<p>B</p>  <p>M6x50mm 4x</p>	<p>C</p>  <p>8x</p>	
	<p>D</p>  <p>M5 1x</p>			
	 <p>① x1</p>	 <p>② x1</p>	 <p>③ x1</p>	
 <p>x1</p>  <p>5min</p>	 <p>④ x1</p>	 <p>⑤ x1</p>		
<p>1</p>  <p>②</p> <p>③</p>	<p>2</p>   <p>④</p> <p>⑤</p> <p>C</p> <p>A</p> <p>D</p> 			
<p>3</p>  <p>①</p> 	<p>4</p>  			
  	<p>HARBORE DC1145 1/1</p>			