






SANTI/ SICILIA




I



II



H=150mm




Ax5

H=150mm



Bx1

M6x25




Cx10

Ø6mm





Dx10




Ex1

1




I

II





E




B


SANTI/ SICILIA





2










3





SANTI/ SICILIA




4




SANTI/ SICILIA




I



II




H=150mm




Ax5

H=150mm



Bx1

M6x25




Cx10

Ø6mm




Dx10





Ex1


1




I



B





E




II


SANTI/ SICILIA





2










3





SANTI/ SICILIA




4




SANTI/ SICILIA



5



SANTI



SICILIA