




















 <p>NOPE MC-6009H-F-1</p>	<p>A</p>  <p>M6X25mm 6X</p>	<p>B</p>  <p>M6X16mm 4X</p>	<p>C</p>  <p>M6X15mm 10X</p>	<p>D</p>  <p>10mm 1X</p>	
	<p>E</p>  <p>1X</p>	<p>F</p>  <p>M5 1X</p>			
	 <p>① X1</p>	 <p>② X1</p>	 <p>③ X1</p>	 <p>④ X1</p>	
 <p>X1</p>  <p>5min</p>	 <p>⑤ X2</p>	 <p>⑥ X1</p>	 <p>⑦ X1</p>	 <p>⑧ X5</p>	
<p>1</p> 	<p>2</p> 	<p>3</p> 			
<p>4</p> 	<p>5</p> 	<p>6</p> 